

GARDENING**CLEANING RO WATER POINT**

CLEANING RESTROOMS- GIRLS



CLEANING REST ROOMS BOYS



GARBAGE COLLECTION





RO WATER MAINTENANCE





GENERATOR ROOM



FILLING NAPKIN VENDOR MACHINE



MAINTENANCE REGISTER

| SL. NO. | DATE | COMPLAINTS | REPORTED BY | ACTION TAKEN | CLOSED ON | SIGNATURE |
|---------|------------|---|--|--|-----------|-----------|
| 509 | 30.8.2022 | D Block - Ground floor Room no. 60 - window glass to be replaced | DR. THEMAMOZHIL S Asst. Prof & Head B.com & S - Shift II | Done | 4/9/22 | 8/ |
| 10 | 30/8/22 | Need Green Board. Room no - 60 D block - Ground floor | DR. THEMAMOZHIL S Asst. Prof & Head B.com & S - Shift II | Pending | | |
| 11 | 20/8/22 | D. Block 3rd floor MCA - LAB one monitor is not working | Mr. Jayasankar | Completed New Monitor replaced. | 30/8/22 | AKS |
| 12 | 30.08.2022 | மொத்தம்மொன் டீஸ்டர் தெரவென்டு டிசுஸென்டு (தெரவென்டு டிசுஸென்டு பென்டு) | D.Dhananjayan. | Done | 8/9/22 | 8/ |
| 13 | 30.08.2022 | SC/ST Scholarship Room System Not working. | D.Dhananjayan. | Cpu replaced. Now working successfully. | 06/09/22 | AKS |

PCAS/HK

| SL. NO. | DATE | COMPLAINTS | REPORTED BY | ACTION TAKEN | CLOSED ON | SIGNATURE |
|---------|------------|--|--|--|-----------|-----------|
| 14 | 09/10/22 | D-Block - Lift - 2nd floor Button (not working) loose connection. | Sureth. IT - Tech. Dept... | 8/10/22 | Done | 8/ |
| 15 | 08/10/22 | Campus - Internet Very slow. | Sureth. IT - Tech. Dept. | New Jio router / Connect 2 firewalls. Now working New firewall fixed for (campus). | 25/10/22 | AKS |
| 16 | 10/10/2022 | Kindly repair the Television in Student Cafeteria. It can be used to update about upcoming programmes in college. | Mr. Prithvish Mr. Rasool SAC, Coordinator & Student Council | Pending. Now TV fixed. Now working successfully. | 10/12/22 | AKS |
| 17 | 10/10/22 | Psychology Dept. Laptop very slow... | Sureth P IT - Tech. Dept. | charger fault & HDD upgraded. (HDD - SSD). SSD (HDD) changed & OS installed. Now working successfully. | 25/10/22 | AKS |
| 18 | 10/10/22 | Sanitary napkin vending machine - not working properly (first floor D-Block) | DR. THEMAMOZHIL S B.com. CS - Shift II | Pending Thormet Company | | |

PCAS/HK